

Appendix A. Project Site Representative Photographs



Photo 1. Aerial view of northern of Bank property – looking northeast
(May 14, 2021)



Photo 2. Aerial view of northeastern portion of Bank property – looking southeast
(May 14, 2021)

Appendix A. Project Site Representative Photographs



Photo 3. Existing access road along west boundary of property - Mellin Levee through center of photo along fence line to west of access road
(May 4, 2022)



Photo 4. Looking east from western project boundary at grassland and clay flat habitat
(August 5, 2022)

Appendix A. Project Site Representative Photographs



Photo 5. Looking west across Bank property at managed marsh habitat
(August 5, 2022)



Photo 6. Looking west across Bank property at irrigated pasture
(March 14, 2019)

Appendix A. Project Site Representative Photographs



Photo 7. Looking east along Watson Hollow Slough and adjacent berm along northern boundary
(August 5, 2022)



Photo 8. Existing utility line in northern portion of Bank property
(August 5, 2022)

Appendix A. Project Site Representative Photographs



Photo 9. Existing water management structure in Watson Hollow Slough along north boundary
(August 5, 2022)



Photo 10. Existing water management structure to allow tide waters onto Bank property
(August 5, 2022)

Appendix A. Project Site Representative Photographs



Photo 10. Looking north at location of proposed low water crossing structure on State Route 65
(August 31, 2023)



Photo 10. Looking east at location of proposed low water crossing and tidal channel
(August 31, 2023)