

Appendix A-1. Representative Project Site Photographs



Photo 1. Aerial view of northern portion of Project site – looking northeast
(May 14, 2021)



Photo 2. Aerial view of northeastern portion of Project site – looking southeast
(May 14, 2021)

Appendix A-1. Representative Project Site Photographs



Photo 3. Existing access road along west boundary of Project site – Mellin Levee through center of photo along fence line to west of access road
(May 4, 2022)



Photo 4. Looking east from western Project boundary at grassland and clay flat habitat
(August 5, 2022)

Appendix A-1. Representative Project Site Photographs



Photo 5. Looking west across Project site at managed marsh habitat
(August 5, 2022)



Photo 6. Looking west across Project site at irrigated pasture
(March 14, 2019)

Appendix A-1. Representative Project Site Photographs



Photo 7. Looking east along Watson Hollow Slough and adjacent berm along northern boundary
(August 5, 2022)



Photo 8. Existing utility line in northern portion of Project Site (to be removed)
(August 5, 2022)

Appendix A-1. Representative Project Site Photographs



Photo 9. Existing utility line in northern portion of Bank property
(August 31, 2023)



Photo 10. Looking east at location of proposed low water crossing and tidal channel
(August 31, 2023)

Appendix A-2. Representative Photographs of Offsite Utility Improvement Work Areas (June 25, 2024)



Pole #1 and Pull Site

Location: 38.188459, -121.674041

Habitat in Work Area: Non-native grasses/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



Pole #2

Location: 38.188386, -121.675020

Habitat in Work Area: Non-native grasses/ruderal, blackberry

Sensitive Habitat Nearby: Emergent marsh and open water



Pole #3

Location: 38.188380, -121.676054

Habitat in Work Area: Non-native grasses/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



Pole #4

Location: 38.188381, -121.677127

Habitat in Work Area: Non-native grass/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water

Appendix A-2. Representative Photographs of Offsite Utility Improvement Work Areas (June 25, 2024)



Pole #5

Location: 38.188369, -121.678175

Habitat in Work Area: Non-native grass/ ruderal

Sensitive Habitat Nearby: Emergent marsh, open water



Pole #6

Location: 38.188370, -121.679221

Habitat in Work Area: Non-native grass/ ruderal

Sensitive Habitat Nearby: Emergent marsh, open water



Pole #7

Location: 38.188365, -121.670233

Habitat in Work Area: Non-native grass/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



Pole #8

Location: 38.188368, -121.671173

Habitat in Work Area: Non-native grass/ ruderal

Sensitive Habitat Nearby: Emergent marsh and open water

Appendix A-2. Representative Photographs of Offsite Utility Improvement Work Areas (June 25, 2024)



Pole #9 and pull site

Location: 38.188375, -121.682164

Habitat in Work Area: Non-native grass/ruderal

Sensitive Habitat Nearby: Emergent marsh and open water



Pole #10 (near Highway 84)

Location: 38.183025, -121.666647

Habitat in Work Area: Non-native grass/ruderal

Sensitive Habitat Nearby: Emergent marsh, open water, riparian



Proposed Access Road – easternmost access road on existing graveled farm road



Proposed Laydown Area - Disturbed area formerly used for staging farm equipment and hay